

USER MANUAL / MANUAL PËRDORIMI
BEDIENUNGSANLEITUNG / ПАСПОРТ НЗДЕПНЯ




EN Mounting instructions
DE Montageanleitung
RU Инструкция по монтажу

FR Instruction de montage
AL Udhëzimet e përdorimit
ESP Instrucciones de montaje

GR Συναρμολογησης
RO Instrucțiunile de montaj
BG Ръководство за монтаж

RS Uputstvo za montažu
UA Інструкція по монтажу
AR تعليمات التثبيت



MODEL NO	INPUT VOLTAGE(VAC)	POWER (W)	IP	WORK TEMPERATURE(°C)	WORK HUMIDITY(RH)	CCT
LT64-09102	220-240	100	IP65	-20°C/+40°C	<%93	3000K
LT61-09112	220-240	100	IP65	-20°C/+40°C	<%93	4200K
LT61-09132	220-240	100	IP65	-20°C/+40°C	<%93	6400K
LT64-09402	220-240	150	IP65	-20°C/+40°C	<%93	3000K
LT64-09412	220-240	150	IP65	-20°C/+40°C	<%93	4200K
LT61-09432	220-240	150	IP65	-20°C/+40°C	<%93	6400K
LT64-09602	220-240	200	IP65	-20°C/+40°C	<%93	3000K
LT64-09612	220-240	200	IP65	-20°C/+40°C	<%93	4200K
LT61-09632	220-240	200	IP65	-20°C/+40°C	<%93	6400K
LT64-09802	220-240	400	IP65	-20°C/+40°C	<%93	3000K
LT64-09812	220-240	400	IP65	-20°C/+40°C	<%93	4200K
LT64-09832	220-240	400	IP65	-20°C/+40°C	<%93	6400K

